



Tech Info Library

Apple IIC Serial Loopback Cable: Pinouts (10/94)

Revised: 10/18/94
Security: Everyone

Apple IIC Serial Loopback Cable: Pinouts (10/94)

=====

Article Created: 27 July 1985
Article Reviewed/Updated: 18 October 1994

TOPIC -----

This article describes the pinouts for the IIC serial loopback cable.

DISCUSSION -----

Below are the pin configurations for the Apple IIC serial loopback cable:

Modem port	Printer port
------------	--------------

1	to	5
5	to	1
2	to	4
4	to	2

Ground the connector shields together.

Article Change History:

18 Oct 1994 - Reviewed for technical accuracy, revised formatting.

Support Information Services

Copyright 1988-94 Apple Computer, Inc.

Tech Info Library Article Number:1218